

DAILY MARITIME INCIDENT UPDATE

Information Fusion Center-Colombo




Information Fusion Center
Colombo
Sri Lanka

Date 2026.02.13

WEATHER FORECAST



Weather Forecast for next 24 hrs



FLEET FORECAST

Fleet Forecast for Area - E

Issued by the National Meteorological Center, Department of Meteorology Sri Lanka.

Valid period: 2026.02.13/0600UTC to 2026.02.13/1400UTC

Issued at 0000UTC on 2026.02.13

To: CBO Radio/Fisheries/SL Navy/CBO Port/Coast Guard

Shear line is approximately along : EQ 60E, 01S 70E, 01N 80E, 03N 90E, 02N 100E

ITCZ is approximately along : 07S 60E, 08S 70E, 09S 80E, 7S 90E, 08S 100E

Weather:

OCNL Showers / T'Showers in sections : 10, 40, 45, 60, 65

SCT Showers / T'Showers in sections : 15, 20, 30, 35, 50, 55, 70, 75, 80, 85

ISOL Showers / T'Showers elsewhere.

Winds:

North of Shear line

West of 75E: NE'ly / (10-20)kts.

East of 75E: NE'ly or E'ly / (10-20)kts; gusting up to 25 kts in section 05, 10

In-between Shear line and ITCZ

West of 80E: NW'ly to W'ly / (10-20)kts; gusting up to 25 kts in section 40, 45, 60, 65

East of 80E: W'ly to SW'ly / (10-20)kts.

South of ITCZ: SE'ly / (10-20)kts.

Seas:

Fairly rough, rough at times in sections : 05, 40, 60, 65

Moderate, fairly rough at times in sections : 10, 45

Moderate in sections : 15, 25, 30, 50, 55, 70, 80

Slight to Moderate elsewhere.



NOTE: Seas can be temporarily very rough during thundershowers.

- Source: 1. <https://meteo.gov.lk> 2. <https://www.srilankaview.com/weather.htm>

CYCLONE




Tropical Cyclone "Gezani"



• Source: <https://www.metoc.dc3n.navy.mil/jtwc/jtwc.html>



SUMMERY (MARITIME INCIDENT)



CATEGORY	NO
Maritime Incidents	03
Piracy & Armed Robbery	NIL
Smuggling	NIL
IUU Fishing	NIL
Narcotic	NIL
Irregular Human Migration	NIL
Marine Environment Pollution	NIL
Other	NIL
Total Incidents	03


MARITIME INCIDENTS



11 Feb/One Injured After Tanker–Fishing Boat Collision Off Kobe Coast/Japan

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.02.11	Japan	Off Kobe Coast	Collision	Name – MARUOKA MARU Type: Tanker IMO: 9882774	In a collision the captain of the fishing vessel sustained a head injury and was hospitalized for treatment and evaluation. The Kobe Coast Guard initiated an investigation into the incident..

The incident occurred at approximately 0015 hrs local time when the tanker’s captain reported the collision to the Kobe Coast Guard. Both vessels sustained bow damage however no fuel leakage was observed. MARUOKA MARU later continued its voyage to Kure.



Source -: <https://www.marinetraffic.com/en/maritime-news/14/accidents/2026/12692/one-injured-after-tanker-fishing-boat-collision-off-kobe-coa>


MARITIME INCIDENTS



11 Feb/15 killed after passenger ferry capsizes in Northern Sudan/Sudan

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.02.11	Sudan	River Nile State	Capsizing	Wooden Boat	while local residents and civil defense forces are continuing to search for the remaining missing passengers

The wooden boat carrying over 27 passengers from the villages of Tayba Al-Khawad and Deim Al-Qarai, capsized due to high waves. Civil defense units recovered more than 15 bodies with eight survivors while four people are still missing.



Source -: <https://en.mehrnews.com/news/241715/15-killed-after-passenger-ferry-capsizes-in-Northern-Sudan>


MARITIME INCIDENTS



11 Feb/Russia Rescues Disabled Bulk Carrier in Sea of Japan/Russia

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.02.11	Russia	Nakhodka	Rescue	Name :TAI ZE XING 319 Type : Cargo Flag : Panama	According to authorities, TAI ZE XING 319 arrived safely at Vladivostok on 12 February, where it was berthed. All the crewmembers aboard the vessel were reported safe.

According to the agency press release, the Panama-flagged bulk carrier TAI ZE XING 319 lost propulsion while sailing in neutral waters en route from Nakhodka and was unable to proceed under its own power. In response to the situation, the rescue tug Lazurit was dispatched to the scene and secured the vessel before commencing towing operations. Over the course of the operation, the tug ensured the safe transit of the bulk carrier to port.



Source -: <https://en.mehrnews.com/news/241715/15-killed-after-passenger-ferry-capsizes-in-Northern-Sudan>



Information Fusion Center Colombo Sri Lanka

DISCLAIMER

This information, drawn from various publicly accessible open sources, is disseminated solely to provide situational awareness to national and international stakeholders. As the information originates from open sources, no independent verification has been conducted, and IFC Colombo assumes no responsibility for its accuracy, validity, or completeness.

The Officer Incharge
Information Fusion Centre - Colombo
Naval Headquarters, Colombo, Sri Lanka
+94 11 719 480 6
+94 74 120 4829
ifc@navy.lk
ifc.cbo@gmail.com