

DAILY MARITIME INCIDENT UPDATE

Information Fusion Center-Colombo




Information Fusion Center
Colombo
Sri Lanka

Date 2026.06.11

WEATHER FORECAST



Weather Forecast for Next 24 hrs



FLEET FORECAST

Fleet Forecast for Area - E

Issued by the National Meteorological Center, Department of Meteorology Sri Lanka.

Valid period: 2026.06.11/0600UTC to 2026.06.11/1400UTC

Issued at 0000UTC on 2026.06.11

To: CBO Radio/Fisheries/SL Navy/CBO Port/Coast Guard

Shear line is approximately along : EQ 60E, 03S 70E, 03S 80E, 03S 90E, 02N 100E

Weather:

OCNL Showers / T'Showers in sections : 05, 15, 35, 60, 65, 75

SCT Showers / T'Showers in sections : 00, 10, 25, 30, 40, 45, 50, 55, 70, 80

ISOL Showers / T'Showers elsewhere

Winds:

North of Shear line:

West of 77E: W'ly to SW'ly/ (10-20)kts; gusting up to (25-30) kts in section 05.

East of 77E: SW'ly/ (15-20)kts; gusting up to (25-35) kts in sections 10 and 15.

South of Shear line:

SE'ly to S'ly / (10-20)kts

Seas:

Rough to very rough in Section : 05, 10, 15

Fairly rough, rough at times in Sections : 00, 25, 30


Moderate in Sections : 20, 35, 60, 65, 75, 80, 85

Slight to moderate elsewhere.

NOTE: Seas can be temporarily very rough during thundershowers.

- Source: 1. <https://meteo.gov.lk> 2. <https://www.srilankaview.com/weather.htm>

CYCLONE



• Source: <https://www.metoc.dc3n.navy.mil/jtwc/jtwc.html>

SUMMARY (MARITIME INCIDENT)



CATEGORY	NO
 Maritime Incidents	01
 Piracy & Armed Robbery	01
 Smuggling	NIL
 IUU Fishing	NIL
 Narcotic	NIL
 Irregular Human Migration	NIL
 Marine Environment Pollution	01
 Other	NIL
Total Incidents	03


MARITIME INCIDENTS



07 Jun/ Luxury Superyacht Engulfed in Flames at Sentosa Cove Marina/ Singapore

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.07	Singapore	Sentosa Cove	Fire/Folding/Explosion	Luxury Yacht	A luxury Yacht caught fire at Sentosa Cove on Sunday morning, producing thick black smoke and attracting the attention of local residents, hotel guests, and nearby boaters.

The fire erupted around 0810hrs on June 7 at 11 Cove Drive, involving a Yacht docked at a pontoon, which was fully engulfed in flames upon Firefighters' arrival, as reported by the Singapore Civil Defence Force (SCDF).



Source - : <https://theindependent.sg/scdf-luxury-superyacht-catches-fire-at-sentosa-cove-marina-sending-thick-black-smoke-into-the-air-while-fully-engulfed-in-flames/>


PIRACY & ARMED ROBBERY



10 Jun/ Six Armed Men Approach Cargo Vessel, Exchange Fire with Security Team/ Yemen

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.10	Yemen	Southwest of Balhaf	Armed Robbery	Cargo Vessel	Authorities are investigating an incident and have advised vessels to transit with caution, reporting any suspicious activity to UKMTO.

UKMTO reported an incident 88 nm southwest of Balhaf, Yemen, where a cargo vessel was approached by a small craft carrying six armed individuals. An exchange of fire occurred between the small craft and the cargo vessel's Armed Security Team, leading the small craft to retreat.




Source - : <https://en.mehrnews.com/news/245228/Maritime-incident-reported-off-Yemen-coast>



09 Jun/ Sunken Cargo Vessel Triggers Oil Spill Cleanup/ Philippine

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.09	Philippine	La Virgen Milagrosa	Oil Spill	Name - MSCI 1	The vessel arrived from Omnico Port in Currimao with a legal transport permit issued by the Department of Environment and Natural Resources, according to Dabalos.

On Tuesday, personnel, government workers and volunteers worked to contain an oil spill after the cargo vessel MSCI 1 ran aground in Barangay La Virgen Milagrosa, Badoc, Ilocos Norte. The multiagency response team, including the Philippine Coast Guard and local government, met to address the situation. Provincial Environment and Natural Resources Officer Victor Dabalos directed the ship manager to seal the engine leak urgently to protect fisheries and marine life.



Source -: <https://mb.com.ph/2026/06/09/sunken-cargo-vessel-triggers-oil-spill-cleanup>



Information Fusion Center Colombo Sri Lanka

DISCLAIMER

The information in this report has been sourced from various internal and external parties, including international and local stakeholders, maritime agencies, and open sources. The report analyzes incidents to identify trends and discrepancies, aiming to improve the safety and security of mariners and seafarers. While efforts have been made to ensure data accuracy, users should exercise due diligence. Some incident locations may be approximate. IFC-Colombo requests stakeholders' cooperation in reporting incidents for more accurate analysis of maritime threats. The views expressed in this report do not reflect those of the Sri Lanka Navy or Government of Sri Lanka.

The Officer Incharge
Information Fusion Centre
Colombo 01,
Sri Lanka.
+94 11 719 480 6
+94 74 120 4829
ifc@navy.lk
ifc.cbo@gmail.com