

DAILY MARITIME INCIDENT UPDATE

Information Fusion Center-Colombo




Information Fusion Center
Colombo
Sri Lanka

Date 2026.06.30

WEATHER FORECAST



Weather Forecast for Next 24 hrs



FLEET FORECAST

Fleet Forecast for Area - E

Issued by the National Meteorological Center, Department of Meteorology Sri Lanka.

Valid period: 2026.06.30/0600UTC to 2026.06.30/1400UTC

Issued at 0000UTC on 2026.06.30

To: CBO Radio/Fisheries/SL Navy/CBO Port/Coast Guard

Shear line is approximately along : 01N 60E, EQ 70E, 03S 80E, 02S 90E, 03S 100E

Weather:

OCNL Showers / T'Showers in sections: 05, 15, 30, 35, 50, 55, 65, 70

SCT Showers / T'Showers in sections : 00, 10, 20, 45, 75, 80, 85

ISOL Showers / T'Showers elsewhere.

Winds:

North of Shear line:

West of 75E: SW'ly to W'ly / (10-20) kts; gusting up to (20-25) kts in sections 00.

East of 75E: SW'ly / (15-20) kts; gusting up to (25-30) kts in sections 05, 10, 15, 25, 30.

South of Shear line:

SE'ly/ (10-20) kts; gusting up to 25 kts in sections 65, 70, 80, 85.

Seas:

Rough , very rough at times in section : 05, 10

Fairly rough, rough at times in Sections : 15, 30, 70, 80, 85

Moderate, fairly rough at times in Sections : 00, 25, 65

Moderate in Sections : 35

Slight to moderate elsewhere.


NOTE: Seas can be temporarily very rough during thundershowers.

• Source: 1. <https://meteo.gov.lk> 2. <https://www.srilankaview.com/weather.htm>



CYCLONE


Tropical Cyclone



• Source: <https://www.metoc.dc3n.navy.mil/jtwc/jtwc.html>



SUMMERY (MARITIME INCIDENT)



CATEGORY	NO
Maritime Incidents	03
Piracy & Armed Robbery	NIL
Smuggling	NIL
IUU Fishing	NIL
Narcotic	NIL
Irregular Human Migration	NIL
Marine Environment Pollution	NIL
Other	NIL
Total Incidents	03


MARITIME INCIDENTS



28 Jun/ Malta-Flagged Tanker Towed to Safety After Engine Failure Off Greece/ Greece

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.28	Greece	Northeast of Psathoura	Mechanical breakdown/ Engine Failure/ No Communication	Name-YM JUPITER Type -Tanker IMO: 9291597	Following the incident, the Port Authority of Alonissos sanctioned the vessel's captain for not promptly notifying the relevant port authority of the mechanical failure, violating Greek maritime regulations.

On 28 Jun 26, the Malta-Flagged oil tanker YM JUPITER was towed to Turkish anchorage after experiencing mechanical failure near Psathoura, Greece. All 17 Turkish crew members were safe, and no pollution occurred. The tanker lost propulsion while in transit, prompting the Greek maritime authority to deploy a rescue tug for assistance, which successfully towed the vessel to Canakkale Anchorage, Turkey.



Source -: <https://www.marinetraffic.com/en/maritime-news/14/accidents/2026/13045/malta-flagged-tanker-towed-to-safety-after-engine-failure-of>


MARITIME INCIDENTS



27 Jun/ Indian Coast Guard Stabilizes Flooded Cargo Vessel Off Tamil Nadu/ India

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.27	India	Off Tiruchendur	Capsizing/ Sinking	Name - SITTHAA Type - Other IMO : 8923909	Following the alert, the Indian Coast Guard deployed the ICG ship Atulya to aid a distressed vessel. A specialized boarding team collaborated with salvage experts to conduct emergency repairs and dewatering operations, successfully managing to control the flooding.

The Comoros-Flagged cargo vessel SITTHAA suffered flooding in multiple compartments off Tiruchendur Coast in India, on 27 Jun 26 prompting immediate response from the Indian Coast Guard. All the crew were reported safe in the incident.



Source -: <https://www.marinetraffic.com/en/maritime-news/14/accidents/2026/13044/indian-coast-guard-stabilizes-flooded-cargo-vessel-off-tamil>


MARITIME INCIDENTS



27 Jun/ Greece-Flagged Ro-Ro Ferry Refloats After Grounding Off Milos/ Greece

INCIDENT DATE	COUNTRY/REGION	LOCATION	SUB CATEGORIES	VESSEL DETAILS	ADDITIONAL DETAILS
2026.06.27	Greece	Off Milos	Grounding/ Standing	Name- KISSAMOS Type- Passenger IMO: 9035876	The Hellenic Coast Guard sent a response team, and a diver inspected the vessel's hull, finding no damage. The crew restored propulsion, allowing the ferry to refloat and return safely to Milo.

The Ro-Ro passenger ferry Kissamos refloats after grounding off Milos, Greece, on 27 Jun 26. There were no injuries or pollution reported. The ferry was on a scheduled route from Piraeus to Chania with 1,246 passengers and 108 crew when it experienced a technical fault leading to a temporary loss of propulsion, causing it to drift into shallow waters and ground.



Source -: <https://www.marinetraffic.com/en/maritime-news/14/accidents/2026/13042/greece-flagged-ro-ro-ferry-refloats-after-grounding-off-milo>



Information Fusion Center Colombo Sri Lanka

DISCLAIMER

The information in this report has been sourced from various internal and external parties, including international and local stakeholders, maritime agencies, and open sources. The report analyzes incidents to identify trends and discrepancies, aiming to improve the safety and security of mariners and seafarers. While efforts have been made to ensure data accuracy, users should exercise due diligence. Some incident locations may be approximate. IFC-Colombo requests stakeholders' cooperation in reporting incidents for more accurate analysis of maritime threats. The views expressed in this report do not reflect those of the Sri Lanka Navy or Government of Sri Lanka.

The Officer Incharge
Information Fusion Centre
Colombo 01,
Sri Lanka.
+94 11 719 480 6
+94 74 120 4829
ifccolombo@navy.lk
ifc.cbo@gmail.com